Solutions

ECE321/ECE595 Exam 3 Spring 2013

Notes: You must show work for credit.

This exam has 5 problems and 13 pages.

The last page has handy trig facts.

Note that problem 2 is different specifications depending on if you are in ECE321 or ECE595

Good luck!

$$n_{bs} = -100\cos(6\phi_{sm})$$

$$n_{ar} = -10\sin(6\phi_{rm})$$

$$P = 12$$

where ϕ_{sm} is position measured from the stator axis and ϕ_{rm} is position measured from the rotor axis. In this machine the axis definitions are arranged such that

$$\phi_{rm} = \phi_{rm} + \theta_{rm}$$

The machine is 10 cm long, the stator radius is 5 cm, and the airgap is constant and is 1 mm. Express the mutual inductance between the b-phase of the stator and the a-phase of the rotor in terms of θ_{rm} . The permeability of free space is $4\pi 10^{-7}$ H/m.

$$W_{bs} = \frac{1}{2} \int_{0}^{2\pi/2} (-100 \cos(6\phi_{sm})) d\phi_{sm}$$

$$- \int_{0}^{\phi_{sm}} (-100 \cos(6\phi_{sm})) d\phi_{sm}$$

$$C' = S$$

$$S' = C$$

$$S = S$$

$$W_{bs} = -\frac{50}{6} \left[\sin(6\phi_{sm}) \right]_{0}^{\pi/6} + \frac{100}{6} \sin(6\phi_{sm}) \right]_{0}^{\phi_{sm}}$$

$$= -\frac{50}{6} \left[\sin(6\phi_{sm}) \right] + \frac{100}{6} \sin(6\phi_{sm}) - 0$$

$$= \frac{100}{6} \sin(6\phi_{sm})$$

$$W_{ar} = \frac{1}{2} \int_{0}^{2\pi/2} (-10 \sin 6\phi_{sm}) d\phi_{rm}$$

$$- \int_{0}^{\phi_{rm}} (-10 \sin 6\phi_{rm}) d\phi_{rm}$$

5

$$W_{ar} = \frac{5}{6} \cos(6 \phi_{rm}) \Big|_{0}^{\pi/6} - \frac{10}{6} \cos(6 \phi_{rm}) \Big|_{0}^{\pi/6}$$

$$= \frac{5}{6} \Big[-1 - 1\Big] - \frac{10}{6} \cos(6 \phi_{rm}) + \frac{10}{6}$$

$$= -\frac{10}{6} \cos6 \phi_{rm}$$

$$= \frac{10}{9} \cos6 \phi_{rm}$$

$$= \frac{10}{9} \Big[\frac{100}{6}\Big] \Big(-\frac{10}{6}\Big) \int_{0}^{\phi_{sm}} \sin(6 \phi_{sm}) \cos(6 \phi_{rm}) d\phi_{sm}$$

$$= -\frac{1000 M_{0} Lr}{36 g} \int_{0}^{\phi_{sm}} \sin(6 \phi_{sm}) \cos(6 \phi_{rm}) d\phi_{sm}$$

$$= -\frac{1000 Lr}{7a g} \int_{0}^{\phi_{sm}} \sin(12 \phi_{sm} - 6 \phi_{rm}) + \sin(6 \phi_{rm}) d\phi_{sm}$$

$$= -\frac{2000 \pi Lr}{7a g} \sin(6 \phi_{rm})$$

$$= -\frac{2000 \pi Lr}{7a g} \sin(6 \phi_{rm})$$

$$= -\frac{5}{48 \times 10^{-4}} \sin(6 \phi_{rm})$$
H

2.) 20 pts. Consider a machine with a round rotor (and therefore a constant airgap). Let ϕ_{sm} denote position measured from the stator in a counter-clockwise direction. For this machine the winding functions and currents are given by

$$w_{as} = 50 \sin \phi_{sm}$$

$$w_{bs} = 50 \cos \phi_{sm}$$

$$i_{as} = 5 \cos(100t)$$

$$i_{bs} = -5 \sin(100t)$$

- Part 1. Determine the air-gap such that the peak flux density will be 1 T. Use this airgap for all remaining parts of this question.
- Part 2. Give a simple expression for the air gap flux density as a wave equation in terms of time and space (ϕ_{sm}) .
- Part 3. What is the speed and direction of the flux density wave?
- Part 4. [ECE595 Only] If the stator resistance is 1 Ohm, the stator radius is 10 cm, and the machine length is 5 cm, what is the a-phase voltage as a function of time.

(3)
$$\frac{d\phi_{sm}}{dt} = 100 \text{ rad/s} (CCW)$$

$$\frac{4}{3} \lambda_{as} = r \int_{0}^{2\pi} W_{as} B d\phi_{sm}$$

$$= r \int_{0}^{2\pi} 50 \sin \phi_{sm} \sin (\phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} 50 \cos (-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) - \cos(2 \phi_{sm} - 100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) + \cos(-100t) d\phi_{sm}$$

$$= \int_{0}^{2\pi} \int_{0}^{2\pi} \cos(-100t) d\phi_{sm}$$

= 78.66 cos (100t + 86,35°)

3) 20 pts. A three phase brushless DC machine has the following parameters: $r_s = 3\Omega$, $L_{ss} = 10$ mH, $\lambda_m = 0.17$ Vs, P = 4. The load torque is given by $T_l = 0.01\omega_{rm}$. It is desired to operate the machine at 4000 rpm. What is the peak machine efficiency possible to satisfy this operating point?

$$W_{rm} = 4000 \, \text{rpm} \left(\frac{2\pi}{\text{rev}} \right) \left(\frac{\text{min}}{\text{Goos}} \right) = 418.88 \, \text{rad/s}$$

$$Te = 0.01 \, w_{rm} = 4.19 \, \text{Nm}$$

$$P_{out} = 1.755 \, \text{KW}$$

$$V_{r} = 837.8 \, \text{rad/s}$$

$$V_{r} = \frac{3}{2} \frac{P}{2} \lambda_{m} = 8.21 \, \text{A}$$

$$V_{r} = \frac{3}{2} \frac{P}{2} \lambda_{m} = 8.21 \, \text{A}$$

$$V_{r} = \frac{3}{2} \left(\frac{P}{2} + \frac{P}{2} + \frac{P}{2} \right) = 2.06 \, \text{kW}$$

$$V_{r} = \frac{P_{out}}{P_{in}} = 85.2 \, \%$$

4) Suppose we have a devices in which

$$\lambda_{abcs} = \mathbf{L}_{ss} i_{abcs}$$

$$\mathbf{L}_{ss} = \begin{bmatrix} 6 & 2 & 2 \\ 2 & 6 & 2 \\ 2 & 2 & 6 \end{bmatrix}$$

Express the q-axis, d-axis, and 0-sequence flux linkage equations in the rotor reference frame. Solve this problem by using the appropriate transformations and performing the needed matrix manipulations. Recall

$$\mathbf{K}_{s}^{r} = \frac{2}{3} \begin{bmatrix} \cos(\theta_{r}) & \cos\left(\theta_{r} - \frac{2\pi}{3}\right) & \cos\left(\theta_{r} + \frac{2\pi}{3}\right) \\ \sin(\theta_{r}) & \sin\left(\theta_{r} - \frac{2\pi}{3}\right) & \sin\left(\theta_{r} + \frac{2\pi}{3}\right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$\begin{bmatrix} \mathbf{K}_{s}^{r} \end{bmatrix}^{-1} = \begin{bmatrix} \cos(\theta_{r}) & \sin(\theta_{r}) & 1 \\ \cos(\theta_{r} - \frac{2\pi}{3}) & \sin(\theta_{r} - \frac{2\pi}{3}) & 1 \\ \cos(\theta_{r} + \frac{2\pi}{3}) & \sin(\theta_{r} + \frac{2\pi}{3}) & 1 \end{bmatrix}$$

$$\lambda_{qdos}^{r} = K_{s}^{r} L_{ss} K_{s}^{r-1} |_{qdos}$$

$$= \left[K_{s}^{r} L_{ss_{1}} K_{s}^{r-1} + K_{s}^{r} L_{ss_{2}} K_{s}^{r-1} \right] |_{qdos}$$

$$Term_{1}$$

$$Term_{2}$$

| The following are worth 2 points each. No equations allowed – explain verbally. | |
|---|---|
| 5a) | Using the definitions we had in class, what is the difference between n_{as} and w_{as} ? |
| | nas -> conductor density was -> winding function (turns) |
| 5b) | Why might we want to convert the continuous conductor description to a discrete description? |
| | to determine # of conductors in slots so we can build |
| 5c) | What are the chief uses of the winding function? > calculate air gap MMF > compute air gap of fields |
| 5d) | Sompute inductances tields / 3 What is an advantage of a 3-phase machine over a 1-phase machine? |
| , | -> MMF wave only travels in one direction |
| 5e) | In a two phase machine, if the conductor distributions were different (apart from a spatial shift), is it still theoretically possible to achieve a single rotating MMF wave? |
| | -> Yes |
| 5f) | In class we studied a radial surface-mounted permanent ac machine. Name another type of permanent magnet ac machine. |
| | -> radial buried magnet machine |
| 5g) | Name a disadvantage of a permanent magnet ac machine. |
| | fault current, physical robustness |
| 5h) | Why is it important to use a differential voltage probe when measuring the voltage of a open-circuited permanent magnet machine? |
| | the voltage could damage the oscilloscope |
| 5i) | Name the benefits of transforming the machine equations to qd0 variables? |
| | → ac-de → magnetic) name 2 |
| 5j) | Name advantages of current control of permanent magnet ac machines (brushless dc machines) relative to voltage control. |
| | > typically better efficiency > better transient performance 2 |
| | > better transient performance 2 |
| | -) easy to control 12 |

-> robust with respect to some faults

Handy Facts

$$\mu_0 = 4\pi 10^{-7} \text{ H/m}$$

Table A-1 Trigonometric Identities

$$\sin (A \pm B) = \sin A \cos B \pm \cos A \sin B$$

$$\cos (A \pm B) = \cos A \cos B \mp \sin A \sin B$$

$$\cos A \cos B = \frac{1}{2} [\cos (A + B) + \cos (A - B)]$$

$$\sin A \sin B = \frac{1}{2} [\cos (A + B) + \sin (A + B)]$$

$$\sin A \cos B = \frac{1}{2} [\sin (A + B) + \sin (A + B)]$$

$$\sin A + \sin B = 2 \sin \frac{1}{2} (A + B) \cos \frac{1}{2} (A + B)$$

$$\sin A + \sin B = 2 \sin \frac{1}{2} (A + B) \cos \frac{1}{2} (A + B)$$

$$\cos A + \cos B = 2 \cos \frac{1}{2} (A + B) \cos \frac{1}{2} (A + B)$$

$$\cos A + \cos B = 2 \cos \frac{1}{2} (A + B) \sin \frac{1}{2} (A + B)$$

$$\sin 2A = 2 \sin A \cos A$$

$$\cos 2A = 2 \cos^2 A + 1 = 1 + 2 \sin^2 A = \cos^2 A + \sin^2 A$$

$$\sin \frac{1}{2}A = \sqrt{\frac{1}{2} (1 - \cos 2A)} \quad \cos \frac{1}{2}A = \sqrt{\frac{1}{2} (1 + \cos A)}$$

$$\sin^2 A = \frac{1}{2} [1 - \cos 2A) \quad \cos^2 A = \frac{1}{2} [1 + \cos 2A)$$

$$\sin^2 A = \frac{1}{2} [1 - \cos 2A) \quad \cos^2 A = \frac{1}{2} (1 + \cos 2A)$$

$$\sin^2 A = \frac{1}{2} [1 - \cos 2A) \quad \cos^2 A = \frac{1}{2} (1 + \cos 2A)$$

$$\sin^2 A = \frac{1}{2} [1 - \cos 2A) \quad \cos^2 A = \frac{1}{2} (1 + \cos 2A)$$
where
$$C = \sqrt{A^2 + B^2 - 2AB \cos (\phi_2 - \phi_1)}$$

$$\phi_3 = \tan^{-1} \left[\frac{A \sin \phi_1 + B \sin \phi_2}{A \cos \phi_1 + B \cos \phi_2} \right]$$

$$\sin (\omega t + \phi) = \cos \left(\omega t + \phi - \frac{\pi}{2} \right)$$

Taken from, Continuous and Discrete Signal and Systems Analysis, 2nd Edition, by McGillem & Cooper, 1984, CBS College Publishing, and one heck of a good book.

$$\cos(x) + \cos(x - 2\pi/3) + \cos(x + 2\pi/3) = 0$$

$$\sin(x) + \sin(x - 2\pi/3) + \sin(x + 2\pi/3) = 0$$

$$\cos(x)\cos(y) + \cos(x - 2\pi/3)\cos(y - 2\pi/3) + \cos(x + 2\pi/3)\cos(y + 2\pi/3) = \frac{3}{2}\cos(x - y)$$

$$\sin(x)\sin(y) + \sin(x - 2\pi/3)\sin(y - 2\pi/3) + \sin(x + 2\pi/3)\sin(y + 2\pi/3) = \frac{3}{2}\cos(x - y)$$

$$\sin(x)\cos(y) + \sin(x - 2\pi/3)\cos(y - 2\pi/3) + \sin(x + 2\pi/3)\cos(y + 2\pi/3) = \frac{3}{2}\sin(x - y)$$